file

INVESTIGATION REPORT DEPARTMENT OF COUNTY ENGINEER BUILDING AND SAFETY DIVISION COUNTY OF LOS ANGELES

Location of Problem	3314 N. Ray	found Ave.	
Locality			
Description of Problem	Remodel inter		
Requested by		Phone	
Address			
Received by Leslie C		Date	193
Report of Investigation:	plons in	alut 34 (cy	
2md flare			
Investigator	Title	Date_	
Copy Sent To	Title	Date_	
Report Phoned To	Title	Date _	

JOB ADDRESS 3314 Roymond

OWNER.

STOP ALL WORK

You are in violation with the provisions of the County Ordinance as indicated below:
Building Code
Plumbing Code
Mechanical Code
Electrical Code
Zoning Ordinances
Grading Code
DESCRIPTION: CONVOLUTING 1941C
to 2ND floor, GON
REMOLDING
goe need permits
you used paints
work
Submit plans for the work within 10 days to the office listed above and apply for a plan check for the required Permit.
Obtain a Permit within 10 days for the work at the office listed above.
A referral has been made to the Enforcement Section of the Department of Regional

5-3M3

Planning.

MASPECTOR'S SIGNATURE